

## **GOVERNMENT OF ANDHRA PRADESH**

### **ABSTRACT**

Public Services – R&B Department – Irregularities committed by Sri P.Ramesh Babu,EE(R&B) and 2 other officials in executing the work of "Special Repairs to Gara – Chintada road and other 3 works in Srikakulam District-Charges Issued - Punishment of stoppage of one increment without cumulative effect imposed - Orders - Issued.

---

### **TRANSPORT, ROADS AND BUILDINGS (VIG) DEPARTMENT**

**G.O.RT.No. 22**

**Dated: 07.01.2015**

Read the following:

1. From the Advisor, Quality Control for R&B, Letter No.NAC/153/453, dt.11-02-2008.
2. From the Engineer-in-Chief,(R&B) Administration Letter No.375/VC(2)/2008-1-3, dt.18-10-2012.
3. From ENC(R&B) Admn, Letter.No.375/VC(2)/2008, Dt.10.10.2014.

">&&

#### **ORDER:**

Charges were issued, vide reference second read above, against 1) Sri.P.Ramesh Babu, Executive Engineer(R&B), 2) Sri K. Chandran, Dy.E.E (R&B), 3) Sri R.Ganapathi Rao, A.E.E(R&B), of Srikakulam District, for executing substandard work of "Special Repairs to 1) Km.3/0 to 9/3 of Gara –Chintada; 2) Km.2/0 to 3/440 of Road from Srikakulam Municipal Limits to Pukkalapeta; 3) Km.6/2 to 7/820 of Road from CSP Road to NH5 (via) Ampolu; and 4) Km 0/0 to 2/0 & 7/0 to 8/0 of NH5 to G-C Road and (Package work)"in Srikakulam District, in 2008; and, on this, the charged officers they submitted their WSD,through reference 3<sup>rd</sup> read above, denying the charges.

2. Government,after careful examination of the Written statements of defence of the charged officers, observe that the charged officers, were negligent in recording correct measurements in M.Book; they did not maintain cement log books, and also did not conduct required Q.C Tests; and, hence, decide and warn concerned Q.C officials, to be more careful in future, as there is a shortfall in quality control tests and that no QC tests were done for M20 concrete cement, in respect of Special Repairs to 1) Km.3/0 to 9/3 of Gara –Chintada; 2) Km.2/0 to 3/440 of Road from Srikakulam Municipal Limits to Pukkalapeta;3) Km.6/2 to 7/820 of Road from CSP Road to NH5 (via) Ampolu; and 4) Km 0/0 to 2/0 & 7/0 to 8/0 of NH5 to G-C Road and (Package work)" in Srikakulam District; and, also hereby impose a punishment of stoppage of one increment without cumulative effect against (1) Sri P.Ramesh Babu, the then Executive Engineer(R&B), Srikakulam;(now Deputy Superintending Engineer(R&B), Eluru; (2) Sri K.Chandran, the then Deputy Executive Engineer,(now EE, R&B, Visakhapatnam); and, (3) Sri R.Ganapathi Rao, the then Assistant Executive Engineer (now Deputy Executive Engineer ,Special Sub- Division,Srikakulam).

3. The Engineer-in-Chief (R&B), Administration, shall take necessary further action in the matter accordingly.

(BY ORDER AND IN THE NAME OF THE GOVERNOR OF ANDHRA PRADESH)

B.SAM BOB,  
PRINCIPAL SECRETARY TO GOVERNMENT

To

The individuals **through** the ENC(R&B), Administration, Andhra Pradesh, Hyderabad  
The ENC(R&B),Administration, Andhra Pradesh, Hyderabad.

**Copy to:**

The Secretary to Vigilance Commissioner, Andhra Pradesh Vigilance Commission, Hyd.  
The Accountant General, Andhra Pradesh, Hyderabad.  
The P.S. to Principal Secretary (R&B),TR&B Department.  
SF/SC.

//FORWARDED BY ORDER//

SECTION OFFICER